Gold Butte National Monument Road Report

Tuesday, May 23, 2023

Road conditions are subject to change due to flooding and other natural and unnatural factors. Contact the Las Vegas Field Office for additional information at (702) 515-5056. Check local weather forecasts before visiting the Monument.

Limit your exposure to heat when 90° (32°C) or hotter. Day time temperatures are expected to regularly exceed 105° until late September. Please use extreme caution while traveling within the Monument during the summer months.

Road Name	Date	Condition	Comments
Gold Butte Road (Paved)	5/9/2023	Deteriorated. First 4-5 miles has sand/silt/gravel washed over road. Sections of deep sand over road. May require 4WD High Clearance.	Clark County, Dept of Public Works conducting work to restore access.
Gold Butte Road (Unpaved)	5/9/203	Normal. Requires 2WD High Clearance.	
Fisherman's Cove Road	3/25/2023	Normal. Requires 2WD High Clearance. Wash crossings subject to erosion.	
Black Butte Road	5/19/2023	Normal. Requires 2WD High Clearance. Wash crossings subject to erosion.	
N. Mud Wash Road	4/15/2023	Normal. Recommend 4WD High Clearance.	
Mud Wash Road	4/15/2023	Deteriorated. Wash boarding common. Rough and deep, soft sand in sections. Recommend 4WD High Clearance.	
Little Finland Road	4/15/2023	Normal. Mostly sandy with section of small rock steps. Require 4WD High Clearance.	
Whitney Pass Road	3/24/2023	Normal. Rocky and rough. Requires 2WD High Clearance.	

St. Thomas Gap Road	2/19/2023	Normal. Requires 2WD High Clearance.	Conditions not reassessed following recent precipitation events.
Devil's Cove Road	2/1/2023	Normal. Requires 2WD High Clearance.	Conditions not reassessed following recent precipitation events.
Babe's Bluff Road	2/19/2023	Normal. Requires 2WD High Clearance.	
Gold Butte Wash Road (Red Bluff Spring Road)	2/19/2023	Normal. Rocky with bedrock exposed in sections. Requires 2WD High Clearance.	
Narrows Rd	2/15/2023	Major wash out and erosion above Mud Wash, near Red Bluff Springs. Impassible.	Do not attempt.
White Rock Road to Cabin Canyon	5/16/2023	Normal. Requires 2WD High Clearance. Wash crossings subject to erosion. Water flowing at Cabin Canyon (unknown CFS).	Cross flowing water with caution.